

**FEDERAL HIGHWAY ADMINISTRATION, Federal Lands Highway
DAMAGE SURVEY REPORT (Supplemental Sheet)**

(Title 23, Federal-Aid System/Federal Domain)

Sheet No: 2 of 4

DSR No: 6554 - 1.44

Disaster No: **WA 2007 - 1FS**

Applicant:
Mt Baker-Snoqualmie N.F.

County:
Snohomish

State:
WA

Inspection Date: **July 2007 w FHWA**

Location of Damage (Route No., Name of Road and Mile Post)
FSR 6554 - Evergreen Road - 1.44

ADT: **NA**



< - - Looking east
Fill slope failure



< - - Looking West

Repair failure with
riprap rock wall.

FEDERAL HIGHWAY ADMINISTRATION, Federal Lands Highway			Sheet No: <u> 2 </u> of <u> 4 </u>
DAMAGE SURVEY REPORT (Supplemental Sheet)			DSR No: <u> 6554 - 1.78 </u>
(Title 23, Federal-Aid System/Federal Domain)			Disaster No: WA 2007 - 1FS
Applicant: Mt Baker-Snoqualmie N.F.	County: Snohomish	State: WA	Inspection Date: July 2007 w FHWA
Location of Damage (Route No., Name of Road and Mile Post) FSR 6554 - Evergreen Road - 1.78			ADT: NA



< - - Looking West
Fill slope failure



< - - Looking East

Repair failure with
riprap rock wall.

FEDERAL HIGHWAY ADMINISTRATION, Federal Lands Highway
DAMAGE SURVEY REPORT *(Supplemental Sheet)*

(Title 23, Federal-Aid System/Federal Domain)

Sheet No: 2 of 4

DSR No: 6554 - 3.67

Disaster No: **WA 2007 - 1FS**

Applicant:
Mt Baker-Snoqualmie N.F.

County:
Snohomish

State:
WA

Inspection Date: **July**
2007 w FHWA

Location of Damage (Route No., Name of Road and Mile Post)
FSR 6554 - Evergreen Road - 3.67

ADT: **NA**



< - - Looking West
Fill slope failure



< - - Looking Downslope

Repair failure with
riprap rock wall.


FEDERAL HIGHWAY ADMINISTRATION
Western Federal Lands Highway Division
DAMAGE ASSESSMENT FORM
(Continuation Sheet)

Sheet No. 2 of 11
Revised: **Revised #2 4-5-08**
Site No: **6554-4.15**
Disaster: **WA 2007-1FS**

Applicant: **MT BAKER-SNOQUALMIE N.F.** County: **Snohomish** State: **WA**

Inspection: **July 2007 w FHWA**

Location of Damage (Route No., Name of Road, Mile Post:
FSR 6554 - Evergreen Road - MP 4.15



< - Looking
up road
southerly



< - Looking
downstream

FEDERAL HIGHWAY ADMINISTRATION, Federal Lands Highway DAMAGE SURVEY REPORT <i>(Supplemental Sheet)</i> (Title 23, Federal-Aid System/Federal Domain)			Sheet No: <u> 2 </u> of <u> 4 </u> DSR No: <u> 6554 - 4.15 </u> Disaster No: WA 2007 - 1FS
Applicant: Mt Baker-Snoqualmie N.F.	County: Snohomish	State: WA	Inspection Date: July 2007 w FHWA
Location of Damage (Route No., Name of Road and Mile Post) FSR 6554 - Evergreen Road - 4.15			ADT: NA



< - - Looking toward
Fill slope failure and
road washout.

Culvert plugged and sent
water across road which
eroded the road and fill
slope. Woody debris can
be seen where cmp inlet
is located.



< - - Looking Downslope

Repair failure with
riprap rock wall.
OR concrete ford
Betterment

FEDERAL HIGHWAY ADMINISTRATION
Western Federal Lands Highway Division
DAMAGE ASSESSMENT FORM
(Continuation Sheet)

Sheet No. 3 of 12

Revised: 04-04-08

Site No: 6554-5.0

Disaster: #REF!

Applicant:
MT BAKER-SNOQUALMIE N.F.

County:
Snohomish

State:
WA

Inspection Date:
July 2007 with FHWA

Location of Damage: (Route No., Name of Rd, Mile Post:
FSR 6554 - Evergreen Road - MP 5.0

Description of Repairs:



< - - Looking uproad
and southerly

< - - 72" pipe arch



< - - Looking toward
the roads
beginning and
northerly